

Town of Bristol
Town Administrator
1 South Street
P.O. Box 249
Bristol, VT 05443
(802) 453-2410 ext. 22
townadmin@bristolvt.org
www.bristolvt.org

November 21, 2018

Ivan Hendee
135 Packard RD
Jericho, VT 05465

Subject: Maintenance of grease trap on premises

Dear Sewer User:

I am writing to bring to your attention to the importance of maintaining the grease trap(s) on your property. The Town of Bristol contracts with the Vermont Utility Management Services (VTUMS) to maintain the Bristol Core Area Sewer System. Through their routine maintenance of the system, they are finding excessive amounts of grease and oil in the septic tank. Not only does this add costs to the system to have it pumped out more frequently, it jeopardizes the function of the entire system and can cause it to fail. Failure of the public sewer system could be catastrophic and costly for all the businesses and residents connected to it.

Enclosed is a copy of the Bristol Core Area Sewer Ordinance for your review. Please take particular note of Article 7, which requires that the property owner provide the Town with records of maintenance of these preliminary treatment facilities. We strongly recommend that grease traps be cleaned at least monthly. We also request that records documenting this maintenance be provided to the Town quarterly based on the following schedule:

Quarter	Date Due
January, February, March	April 15
April, May, June	July 15
July, August, September	October 15
October, November, December	January 15


For guidance and best practices on how to properly maintain your grease trap and maintain regular maintenance records, please contact a trusted plumber or a septic service provider. You can also contact us at 453-2410 or town@bristolvt.org or VTUMS at (802) 377-2316 or info@vtums.com, if you have questions.

Sincerely,

Valerie Capels
Town Administrator

Enclosure

cc: Jen Myers, Town Clerk and Treasurer
Sharon Lucia, Administrative Assistant
VTUMS



Town of Bristol
 Town Administrator
 1 South Street
 P.O. Box 249
 Bristol, VT 05443
 (802) 453-2410 ext. 22
townadmin@bristolvt.org
www.bristolvt.org

November 21, 2018

Snap's Restaurant
 24 Main St
 Bristol, VT 05443

Subject: Maintenance of grease trap on premises

Dear Sewer User:

I am writing to bring to your attention to the importance of maintaining the grease trap(s) on your property. The Town of Bristol contracts with the Vermont Utility Management Services (VTUMS) to maintain the Bristol Core Area Sewer System. Through their routine maintenance of the system, they are finding excessive amounts of grease and oil in the septic tank. Not only does this add costs to the system to have it pumped out more frequently, it jeopardizes the function of the entire system and can cause it to fail. Failure of the public sewer system could be catastrophic and costly for all the businesses and residents connected to it.

Enclosed is a copy of the Bristol Core Area Sewer Ordinance for your review. Please take particular note of Article 7, which requires that the property owner provide the Town with records of maintenance of these preliminary treatment facilities. We strongly recommend that grease traps be cleaned at least monthly. We also request that records documenting this maintenance be provided to the Town quarterly based on the following schedule:

Quarter	Date Due
January, February, March	April 15
April, May, June	July 15
July, August, September	October 15
October, November, December	January 15


For guidance and best practices on how to properly maintain your grease trap and maintain regular maintenance records, please contact a trusted plumber or a septic service provider. You can also contact us at 453-2410 or town@bristolvt.org or VTUMS at (802) 377-2316 or info@vtums.com, if you have questions.

Sincerely,

Valerie Capels
 Town Administrator

Enclosure

cc: Jen Myers, Town Clerk and Treasurer
 Sharon Lucia, Administrative Assistant
 VTUMS



Town of Bristol
 Town Administrator
 1 South Street
 P.O. Box 249
 Bristol, VT 05443
 (802) 453-2410 ext. 22
townadmin@bristolvt.org
www.bristolvt.org

November 21, 2018

Treafort
 PO Box 248
 Bristol, VT 05443

Subject: Maintenance of grease trap on premises

Dear Sewer User:

I am writing to bring to your attention to the importance of maintaining the grease trap(s) on your property. The Town of Bristol contracts with the Vermont Utility Management Services (VTUMS) to maintain the Bristol Core Area Sewer System. Through their routine maintenance of the system, they are finding excessive amounts of grease and oil in the septic tank. Not only does this add costs to the system to have it pumped out more frequently, it jeopardizes the function of the entire system and can cause it to fail. Failure of the public sewer system could be catastrophic and costly for all the businesses and residents connected to it.

Enclosed is a copy of the Bristol Core Area Sewer Ordinance for your review. Please take particular note of Article 7, which requires that the property owner provide the Town with records of maintenance of these preliminary treatment facilities. We strongly recommend that grease traps be cleaned at least monthly. We also request that records documenting this maintenance be provided to the Town quarterly based on the following schedule:

Quarter	Date Due
January, February, March	April 15
April, May, June	July 15
July, August, September	October 15
October, November, December	January 15


For guidance and best practices on how to properly maintain your grease trap and maintain regular maintenance records, please contact a trusted plumber or a septic service provider. You can also contact us at 453-2410 or town@bristolvt.org or VTUMS at (802) 377-2316 or info@vtums.com, if you have questions.

Sincerely,

Valerie Capels
 Town Administrator

Enclosure

cc: Jen Myers, Town Clerk and Treasurer
 Sharon Lucia, Administrative Assistant
 VTUMS



Town of Bristol
 Town Administrator
 1 South Street
 P.O. Box 249
 Bristol, VT 05443
 (802) 453-2410 ext. 22
townadmin@bristolvt.org
www.bristolvt.org

November 21, 2018

Andrew Smith
 Cubber's
 8 Main St
 Bristol, VT 05443

Subject: Maintenance of grease trap on premises

Dear Sewer User:

I am writing to bring to your attention to the importance of maintaining the grease trap(s) on your property. The Town of Bristol contracts with the Vermont Utility Management Services (VTUMS) to maintain the Bristol Core Area Sewer System. Through their routine maintenance of the system, they are finding excessive amounts of grease and oil in the septic tank. Not only does this add costs to the system to have it pumped out more frequently, it jeopardizes the function of the entire system and can cause it to fail. Failure of the public sewer system could be catastrophic and costly for all the businesses and residents connected to it.

Enclosed is a copy of the Bristol Core Area Sewer Ordinance for your review. Please take particular note of Article 7, which requires that the property owner provide the Town with records of maintenance of these preliminary treatment facilities. We strongly recommend that grease traps be cleaned at least monthly. We also request that records documenting this maintenance be provided to the Town quarterly based on the following schedule:

Quarter	Date Due
January, February, March	April 15
April, May, June	July 15
July, August, September	October 15
October, November, December	January 15


For guidance and best practices on how to properly maintain your grease trap and maintain regular maintenance records, please contact a trusted plumber or a septic service provider. You can also contact us at 453-2410 or town@bristolvt.org or VTUMS at (802) 377-2316 or info@vtums.com, if you have questions.

Sincerely,

Valerie Capels
 Town Administrator

Enclosure

cc: Jen Myers, Town Clerk and Treasurer
 Sharon Lucia, Administrative Assistant
 VTUMS



Town of Bristol
 Town Administrator
 1 South Street
 P.O. Box 249
 Bristol, VT 05443
 (802) 453-2410 ext. 22
townadmin@bristolvt.org
www.bristolvt.org

November 21, 2018

William Viens
 2063 West Shore Rd
 Salisbury, VT 05769

Subject: Maintenance of grease trap on premises

Dear Sewer User:

I am writing to bring to your attention to the importance of maintaining the grease trap(s) on your property. The Town of Bristol contracts with the Vermont Utility Management Services (VTUMS) to maintain the Bristol Core Area Sewer System. Through their routine maintenance of the system, they are finding excessive amounts of grease and oil in the septic tank. Not only does this add costs to the system to have it pumped out more frequently, it jeopardizes the function of the entire system and can cause it to fail. Failure of the public sewer system could be catastrophic and costly for all the businesses and residents connected to it.

Enclosed is a copy of the Bristol Core Area Sewer Ordinance for your review. Please take particular note of Article 7, which requires that the property owner provide the Town with records of maintenance of these preliminary treatment facilities. We strongly recommend that grease traps be cleaned at least monthly. We also request that records documenting this maintenance be provided to the Town quarterly based on the following schedule:

Quarter	Date Due
January, February, March	April 15
April, May, June	July 15
July, August, September	October 15
October, November, December	January 15


For guidance and best practices on how to properly maintain your grease trap and maintain regular maintenance records, please contact a trusted plumber or a septic service provider. You can also contact us at 453-2410 or town@bristolvt.org or VTUMS at (802) 377-2316 or info@vtums.com, if you have questions.

Sincerely,

Valerie Capels
 Town Administrator

Enclosure

cc: Jen Myers, Town Clerk and Treasurer
 Sharon Lucia, Administrative Assistant
 VTUMS



Town of Bristol
 Town Administrator
 1 South Street
 P.O. Box 249
 Bristol, VT 05443
 (802) 453-2410 ext. 22
townadmin@bristolvt.org
www.bristolvt.org

November 21, 2018

Sheun Lai Poon
 c/o Wokky's
 17 Main St
 Bristol, VT 05443

Subject: Maintenance of grease trap on premises

Dear Sewer User:

I am writing to bring to your attention to the importance of maintaining the grease trap(s) on your property. The Town of Bristol contracts with the Vermont Utility Management Services (VTUMS) to maintain the Bristol Core Area Sewer System. Through their routine maintenance of the system, they are finding excessive amounts of grease and oil in the septic tank. Not only does this add costs to the system to have it pumped out more frequently, it jeopardizes the function of the entire system and can cause it to fail. Failure of the public sewer system could be catastrophic and costly for all the businesses and residents connected to it.

Enclosed is a copy of the Bristol Core Area Sewer Ordinance for your review. Please take particular note of Article 7, which requires that the property owner provide the Town with records of maintenance of these preliminary treatment facilities. We strongly recommend that grease traps be cleaned at least monthly. We also request that records documenting this maintenance be provided to the Town quarterly based on the following schedule:

Quarter	Date Due
January, February, March	April 15
April, May, June	July 15
July, August, September	October 15
October, November, December	January 15


For guidance and best practices on how to properly maintain your grease trap and maintain regular maintenance records, please contact a trusted plumber or a septic service provider. You can also contact us at 453-2410 or town@bristolvt.org or VTUMS at (802) 377-2316 or info@vtums.com, if you have questions.

Sincerely,

Valerie Capels
 Town Administrator

Enclosure

cc: Jen Myers, Town Clerk and Treasurer
 Sharon Lucia, Administrative Assistant
 VTUMS



Town of Bristol
 Town Administrator
 1 South Street
 P.O. Box 249
 Bristol, VT 05443
 (802) 453-2410 ext. 22
townadmin@bristolvt.org
www.bristolvt.org

November 21, 2018

Savoure'LLC
 26 Main St
 Bristol, VT 05443

Subject: Maintenance of grease trap on premises

Dear Sewer User:

I am writing to bring to your attention to the importance of maintaining the grease trap(s) on your property. The Town of Bristol contracts with the Vermont Utility Management Services (VTUMS) to maintain the Bristol Core Area Sewer System. Through their routine maintenance of the system, they are finding excessive amounts of grease and oil in the septic tank. Not only does this add costs to the system to have it pumped out more frequently, it jeopardizes the function of the entire system and can cause it to fail. Failure of the public sewer system could be catastrophic and costly for all the businesses and residents connected to it.

Enclosed is a copy of the Bristol Core Area Sewer Ordinance for your review. Please take particular note of Article 7, which requires that the property owner provide the Town with records of maintenance of these preliminary treatment facilities. We strongly recommend that grease traps be cleaned at least monthly. We also request that records documenting this maintenance be provided to the Town quarterly based on the following schedule:

Quarter	Date Due
January, February, March	April 15
April, May, June	July 15
July, August, September	October 15
October, November, December	January 15


For guidance and best practices on how to properly maintain your grease trap and maintain regular maintenance records, please contact a trusted plumber or a septic service provider. You can also contact us at 453-2410 or town@bristolvt.org or VTUMS at (802) 377-2316 or info@vtums.com, if you have questions.

Sincerely,

Valerie Capels
 Town Administrator

Enclosure

cc: Jen Myers, Town Clerk and Treasurer
 Sharon Lucia, Administrative Assistant
 VTUMS



Town of Bristol
Town Administrator
1 South Street
P.O. Box 249
Bristol, VT 05443
(802) 453-2410 ext. 22
townadmin@bristolvt.org
www.bristolvt.org

November 21, 2018

Drink Pink
c/o Bob Cat Restaurant
5 Main St
Bristol, VT 05443

Subject: Maintenance of grease trap on premises

Dear Sewer User:

I am writing to bring to your attention to the importance of maintaining the grease trap(s) on your property. The Town of Bristol contracts with the Vermont Utility Management Services (VTUMS) to maintain the Bristol Core Area Sewer System. Through their routine maintenance of the system, they are finding excessive amounts of grease and oil in the septic tank. Not only does this add costs to the system to have it pumped out more frequently, it jeopardizes the function of the entire system and can cause it to fail. Failure of the public sewer system could be catastrophic and costly for all the businesses and residents connected to it.

Enclosed is a copy of the Bristol Core Area Sewer Ordinance for your review. Please take particular note of Article 7, which requires that the property owner provide the Town with records of maintenance of these preliminary treatment facilities. We strongly recommend that grease traps be cleaned at least monthly. We also request that records documenting this maintenance be provided to the Town quarterly based on the following schedule:

Quarter	Date Due
January, February, March	April 15
April, May, June	July 15
July, August, September	October 15
October, November, December	January 15

For guidance and best practices on how to properly maintain your grease trap and maintain regular maintenance records, please contact a trusted plumber or a septic service provider. You can also contact us at 453-2410 or town@bristolvt.org or VTUMS at (802) 377-2316 or info@vtums.com, if you have questions.

Sincerely,

Valerie Capels
Town Administrator

Enclosure

cc: Jen Myers, Town Clerk and Treasurer
Sharon Lucia, Administrative Assistant
VTUMS